BOW DECONSTRUCTION UPDATE

DATE: 8/12/ 2011







PORT PROFILE



TOP VIEW





NOTES:

BUNKER OIL WAS

RELASED AND

CAPTURED BY

SAUSAGE BOOM

WHEN CUTTING

PORT AND STBD

DOUBLE BOTTOM

VENT PIRES AND

SOUNDING TUBES